

C

Meas1:Mkr2 440.000 MHz
1.140



Stop 500.000 MHz

1:Mkr (MHz)	2:Mkr (MHz)	Ohm	Ohm
1: 430.0000 1.162			
2> 440.0000 1.140			
3: 460.0000 1.146			